



BALLY'S CASINO & HOTEL, Tunica

Bally's began installing **Compress Shield™** in early 2001. They had so many problems with the equipment that it was scheduled to be replaced in 2002. They said that during the summers they were constantly going up on the roof to restart units that had gone off line because of high head pressure.

After the introduction of **Compress Shield™** problems with the equipment evaporated. In 2000, Bally's replaced 17/Ea 25 and 35/ton compressors. In 2004 they didn't replace any. This is still the same equipment from 2001, since,

"...everything is cool, maintenance costs are down and energy costs are down..."

they made the decision not to replace the equipment.

Bally's has used **Compress Shield™** to increase ice production, increase cooling capacity on refrigeration and freezers, noise abatement, etc. They have many success stories to tell.

Management told them in 2003 that the electrical rate had gone up but that the bill was going down!

Bally's experience covers the breath of what **Compress Shield™** accomplishes; lowers energy costs, reduces maintenance problems and costs and increases the life of the equipment.

BALLY'S
CASINO TUNICA

Roy Childs
Casino Maintenance