



## HARRAH'S CASINO & HOTEL, Tunica

Harrah's began installing **Compress Shield™** in August of 2002 and completed installation in May 2003. Ricky Atkinson the Harrahs A/C and Refrigeration technician said that amperage readings have been taken as part of normal maintenance for years. **Since treatment of the equipment with Compress Shield the compressors are running significantly lower amperage.** Most of their equipment has two 40/ton compressors in each unit. Mr. Atkinson said that he has noticed that in the summers prior to installation of **Compress Shield™** both compressors in the units would run continuously. In the summers of 2003 and 2004 during routine checks of the equipment most of the time only one compressor is running and the other is usually cool to the touch indicating that it hasn't been operating.

Bill Sivori reported that in 2002 prior to the installation of **Compress Shield™** they changed out 6 compressors (40/tons or larger). Since the completion of the installations in May of 2003 Harrahs has only replaced one compressor and that was an electric utility problem.

Bill Sivori's comment to Mr. Ron Ortiz, CEO  
of Strider-Imperial Tools,

***"Compress Shield™ does  
everything they claim!"***



*Bill Sivori*  
Director of Facilities